

Brewery Creek – Trail and Culvert Washout



Lester River - Pedestrian Bridge Destroyed and Flood Debris



Hartley Park – Damage to Trail and Boardwalk



Lester River Snowmobile Bridge - Undermining



Chester Park Service Road - Washout



Lake Superior Zoo – Retaining Wall Failure



Lester Ski Trail – Culvert Washout



Piedmont Park – Culvert Washout

